

Effective Date: 05.08.2020
Expiry Date: 31.12.2020
Type: Product Update Document
ID: FSA-08-2020
For part numbers: HG3-xx-xxx, ULD-TP-xxx, UH-xx-5-24, THB

PRODUCT HARDWARE UPDATE INFORMATION

05. August 2020

Dear RF elements® customer,

from now on, you might be noticing our antenna hardware screws arriving with a black coating.

Stainless steel hardware is not common in the WISP industry and requires the use of anti-seize lubricant. Therefore, many customers experienced seizing of the screws preventing the re-use of the bracket.

The new black coating on the screws prevents this seizing, improves the user experience, and mounting hardware longevity.



If you have further questions, feel free to contact your Distributor or contact us directly on info@rfelements.com.

Best regards

Tomas Zvolensky
Product Manager